


* Note 1 - record header position before disconnecting HD Activity Led and Reset Switch connectors from HD controller and motherboard

Note 2 - do not install more than one programming jumper at a time. This will damage the board.

Programming Reset Times



Trinity Electronics Systems Ltd
Edmonton, Alberta Canada

PC Watchdog - Installation Diagram

Drawn GSW	Date 26/July/96	Drawing PCWDWRG3.CDR	Rev A0	Sht. 1/1
--------------	--------------------	-------------------------	-----------	-------------